## TOP SECRET IDEALIST

IDEA 0050-68 Copy 7 of 8 10 April 1968

MEMORANDUM FOR THE RECORD

SUBJECT: Resume of Mission SolsE

Mission S018E was alerted on 25 Earch 1968 for a round robin mission with launch and recovery from on 27 March 1968 This mission was flown

Preplanned Rission Data:

Distance

1396 NE

Time to Landing

3+55 Hours

Mission Profile

Eaximum Altitude

Take off Tuel

895 Gallons

Fuel Reserve at Hi Cone

250 Gallons

Targets: The route of this mission was planned to obtain photo coverage of the Cambodia/Thylland border as There were no COMIREA targets covered on this mission.

scheduled. Landing time was Take off was as for a mission duration of four hours.

35×1B

## IDEALIST TOP SECRET

**GROUP 1** 

25X1A

25X1A

25X1C

Excluded from automatic approved For Release 2002/06/13: CIA-RDP68B00724R000200090018-2

downgrading and declassification

## TOP SECRET

IDEA 0050-68 Page 2

a. Target Coverage:

There were so COMIREX targets in the area covered on this mission.

with military activity related to troop and artillery encampments, military equipment and installations, sircraft and sirfields, and road construction. The pilot observed possible construction and a build up near Samrong Airfield. He also noted active grading and leveling on the Thai-Cambodia road in the vicinity of Poipet (1340H 10234E).

25X1C

25X1D

- b. Weather in the target area was as briefed except on the third flight line where the pilot deviated 15 miles right of course due to haze and CAT IV variable III.
- 3. Air Defense Reactions: There were no Air Defense Reactions reported.

6. Photo Analysis: The overall photo analysis on this mission was good with 20 percent cloud cover. The Delta Camera malfunctioned on the last half of the last flight line. The shutter assembly went through the fail safe causing 1-4 slave instrument to shut down. This resulted in loss of stereo effect for the last 30 minutes of camera operation.

IDEALIST TOP SECRET

## TOP SECRET

IDEA 0050-68 Page 3

There	rere	no	aircraft	general	or	flight	instrument	gracueb-
ancie	B .							

8. Communications: Radio and navaids operated satisfactorily. readout at was also satisfactory. 25X1A

Maintenance: Article 385 was flown on this mission.

- 9. Actions to be Taken: Avionics and OEL were tasked to investigate the feasibility of a method of qualifying "L" band signals twice in the Oscar Sierra System before the amber light would come on. This would eliminate many Oscar Sierra low indications resulting from only one sample of a signal. Operations will review and determine the suitability of a one to four number count by the pilot when the Oscar Sierra low light comes on, he will then attempt to evaluate the signal to determine its validity and take appropriate action.
  - 10. Critique for mission 5018E was held on 4 April 1968.

Chief. IDEALIST Division, OSA

25X1A

Attachment - 1
Route Overlay

Route Overlay

ea (10 April 1968)

Distribution:

IDEA/OSA

- /1 D/8A
- #2 D/O/OSA
- #3 SBD/RAD/OSA
- #4 INTEL/OSA
- #5 D/M/OSA
- #6 IDEA/OSA
- #7 BB/08A
- #8 Holdback

IDEALIST TOP SECRET

Approved For Release 2002/06/13: CIA-RDP68B00724R000200090018-2

25X1A

25X1A